


SERVICE BULLETIN #139a November 15, 1996

-Engineering Department-




In order to prevent excessive vibration at Holddown, we are sending a replacement chain to all **MiTek® Cyber Saw®** Owners.

Please replace the chain on both Holddown Assemblies as per figure below and attached drawing. Refer to Cyber Manual for instructions on replacing Holddown chains (Chapter 4).



Materials Needed:

- (2) 18 ft. Chain #50
MiTek® P.N. 554006
- (2) Connector Link #50
MiTek® P.N. 554181



Attached is a revised print of Powered Holddown Assemblies, Stationary and Carriage, showing above update.

Please replace the prints in your manual.

The following customers received the Chain Replacement. All other saws were manufactured with this chain already in place.

- AC Houston Lumber Company SOO3991
- Chambers Truss SOO3996
- MiTek Industries S.A. SOO5146
- Gang-Nail Australia Ltd SOO5091
- Gang-Nail Systems A B S004187
- MiTek Industries Ltd S007056
- Superior Truss And Components SOO7010

The following drawings should be included with this Service Bulletin:

77810C

77776C